



- 4. ADDED AS SECONDARY OPERATION.
 - 2. ALL CAPACITORS IN MICORFARADS, EXCEPT AS NOTED.
 - 1. ALL RESISTORS IN OHMS
- NOTES: UNLESS OTHERWISE SPECIFIED.

CARVIN BX600, BX1200 System Master	
DRAWN BY: GEORGE DREYER	DATE: 30MAY05
APPROVED:	DATE:
PCB NO: 30-42500	REV: E
ASSY. NO: 80-42800	REV: B
NO: 80-42122	DATE: 11AUG06
REVISED BY: GEORGE DREYER	

- Changes from Assembly Rev (B).
- Fan high speed circuit correction. correct shorted jumpers
- Changes from Assembly Rev (C) not made.
- Add resistors for P5 & P8 on BR600
 - correct bias circuit on amp 2
- CHANGES FOR BX1200 ASSEMBLY: 80-42122
- Add Q110, Q210 (Type: MJL 21194).
 - Add R114, Q214 (Type: MJL 21193).
- EX800 Assembly jumpers: B401, B402, B403, B404, B405, B406, B407, B408
- EX1200 Assembly jumpers: B801

